

2. check whether there is any break on cable
before use
3. Overload using is strictly prohibited.
4. keep working temperature under 70°C
for long range operation.

CE 
Made in P.R.C

LAVKRISH Sp. z o.o. o.ul. Jana
Ostrołęga 27/2901-163 Warszawa

BX