

















Only trained personnel may replace or repair seat height adjustment components with energy accumulators.