
型号: GM2 pro

尺寸: 73\*93

材质: 80g铜版纸(折页)


















6.因承载过重造成的脱线或撕裂;

10.产品正常使用过程中发生的老化、脱色、磨损、破裂和其他损耗。

8.有烧损或水浸迹象的产品;



"Lenovo", "thinkplus" 是联想集团所属企业的商标,提及的其他公司、 产品和服务名称可能是其他公司的商标。 版权所有©2022联想集团所属企业和其许可方保留所有权利。

保修声明

产品及随附物料的齐备和外观完好不属于保证范围,您应在接收产品时当场


以上保证是我们就产品做出的全部保证,且仅在中国大陆地区境内适用。本


文件的任何内容均不影响根据法律规定不能排除或限制的消费者权利。


服务监督热线: 400-812-0102


售后邮箱: frank@szeysan.cn


thinkplus














Warranty statement 6.Disconinection or tearing caused by excessive load;

7.Any damage caused by sharp objects;

8.Products with signs of burning of flooding;

9.Damage caused by unauthorized disassembly;

10.Aging,discoloration,abrasion,rupture and other losses that occur during the normal use of the product. 11.If the original identification label of the product is changed or damaged,this guarantee will become invalid. the product is twelve (12) months from the date of purchase ("Warranty Period"), under normal conditions of use due to quality defects damaged, can be repaired free repair;free replacement if ing materials are not within the scope of the guarantee. You should check on the spot and raise objections to any discrepancies. The above guarantees are all guarantees we make regarding the products,and are only applicable in mainland China.Nothing in this document affects consumer rights that cannot be excluded or After-sales mailbox:frank@szeysan.cn "Lenovo", "thinkplus" Is a trademark of a company owned by

Lenovo Group. The names of other companies, products and services mentioned may be trademarks of other companies.

Copyright ©2022 Lenovo Group and its licensors. All rights reserved. The above guarantee does not apply to the following situations: 2.Altering the warranty card and product code does not match the product body;
3.Causes caused by misuse,abuse or improper transportation,use, maintenance or storage obstacles or damage;

5.The zipper and tower buckle are damaged due to excessive force;

thinkplus