Elite Strap With 8000mAh Battery
For Oculus Quest 2

User Manual

CE ♻ Made in China

---

①

Gently pull out the facial interface foam that came with the headset.

②

Install the elastic strap at the top to the slot.

③

Reinsert the facial interface foam and snap it into place.

④

Fasten both sides of the headset with the buckle.

⑤

Secure the top strap through the hole as shown.

⑥

Plug in the battery to charge your headset.

⑦

The length of the elastic band can be adjusted to your needs.

Note:

When the power of the mobile power supply is low,use the Type-C cable to charge it,and it can be used again after it is fully charged.

Basic Parameters:

Battery Type:Li-ion Polymer Battery
Cell Capacoity:3.7V/8000mAh
Output Voltage:DC 5.0V
Input Voltage:DC 5.0V
Output Current:2A(Max)
Input Current:2A(Max)
This product is fully charged in the fastest about 5 hours.