Assembly instruction | Metal wire barchair base

blatt.

Kg **120**

1x

5 min

Included parts

A x1

B x1

C x4

D x4

E x1

1

A

D

C

E

B

2