




VEVOR®
TOUGH TOOLS. HALF PRICE.

HS001

WARNING:
READ INSTRUCTIONS MANUAL BEFORE OPERATING.
1. ALWAYS WEAR EYE PROTECTION.
2. NEVER REACH INTO THE SPINDLE OR TOOL CHANGING AREA WHILE THE MACHINE IS RUNNING.
3. ALWAYS USE THE APPROPRIATE TOOL FOR THE JOB.
4. ALWAYS USE THE APPROPRIATE FEED RATE.
5. ALWAYS USE THE APPROPRIATE CUTTING SPEED.
6. ALWAYS USE THE APPROPRIATE CLAMPING METHOD.
7. ALWAYS USE THE APPROPRIATE SUPPORT METHOD.
8. ALWAYS USE THE APPROPRIATE HOLDING METHOD.
9. ALWAYS USE THE APPROPRIATE HOLDING METHOD.
10. ALWAYS USE THE APPROPRIATE HOLDING METHOD.



CE

RoHS

Technical Support and E-Warranty: www.vevor.com/support
Made in China