






A		M6x80	42
B			42
C		M6x70	6
D		M6x25	6
E		Φ8x20	12


F			2
G		Φ8x30	42
H		Φ4x30	60
I		Φ6x70	12
J			17

step1




A		M6x80	10
B			10
G		Ø8x30	14

step2



A		M6x80	20
B			20
G		Ø8x30	12


step3




I		Φ6x70	12
---	---	-------	----

step4

OPTION A




OPTION B




A		M6x80	2
B			2
C		M6x70	6
E		Φ8x20	6
G		Φ8x30	2

step5




D	 M6x25	6
E	 Ø8x20	6

step6



H	 Ø4x30	60
---	---	----

step7



J		17
---	---	----