


Assembly instructions for the bed frame, including tool requirements, time, and personnel.

**Tools:** An icon shows an Allen key and a wrench inside a circle, with a crossed-out power drill icon next to it, indicating that manual tools are required and power tools should not be used.

**Warning:** A warning triangle with an exclamation mark is positioned above the tool icons.

**Time:** A clock icon is shown next to the text "45'", indicating the estimated assembly time.


**Personnel:** An icon of a person is shown next to the number "2", indicating that two people are required for assembly.



1



L




3




L



4x12



9



2




L




L

K



7




8



K




K




8



K




7




M

1




x 1

2




x 1

3




x 1

4




x 12

5




x 24

6




x 6

7




x 2

8




x 2

9




x 1

A




x 16

B




x 22

C




x 4

D




x 22

E




x 16

F




x 16

G




x 1

H



x 1

I



x 1

J



x 1

K




x 4

L






x 4

M






x 1




1






2





3





4







5






6



7





8






9

H  
  
x 1




10



M



x 1



11 x 12



12

