

- Measure with integrated measuring tips  
OR
- external Probe, 0.5 m cable
- Replaceable Electrodes, 8 mm measuring depth
- External Temperature Probe
- Calibration check
- Automatic power off.
- Battery check

