

**Elite Strap With 8000mAh Battery**  
For Oculus Quest 2



**User Manual**

CE Made in China



①

Gently pull out the facial interface foam that came with the headset.



②

Install the elastic strap at the top to the slot.



③

Reinsert the facial interface foam and snap it into place.



④

Fasten both sides of the headset with the buckle.



⑤

Secure the top strap through the hole as shown.



⑥

Plug in the battery to charge your headset.



⑦

The length of the elastic band can be adjusted to your needs.



**Note:**

When the power of the mobile power supply is low, use the Type-C cable to charge it, and it can be used again after it is fully charged.



**Basic Parameters:**

Battery Type: Li-ion Polymer Battery  
Cell Capacity: 3.7V/8000mAh  
Output Voltage: DC 5.0V  
Input Voltage: DC 5.0V  
Output Current: 2A(Max)  
Input Current: 2A(Max)  
This product is fully charged in the fastest about 5 hours.