

## 使用教程 Using tutorials

Press and hold for 5 seconds to power on  
After the indicator light flashes, it is in the power on state  
Press the button to adjust the temperature when the machine is turned on  
The green indicator is low temperature  
The blue indicator light is medium temperature  
The red indicator is high temperature  
After use, Press and hold for 5 seconds to power off



- 長按5秒按鍵開機
- 指示燈閃爍后為開機狀態
- 開機狀態下單按按鍵調溫
- 綠色指示燈為低溫
- 藍色指示燈為中溫
- 紅色指示燈為高溫
- 使用後長按5秒按鍵開機

導熱迅速  
10分鐘自動休眠  
烙鐵頭/發熱芯便捷更換

Rapid heat conduction  
10 minute automatic sleep  
Easy replacement of soldering iron head / heating core



TYPE-C充電插口  
充滿電后單次可使用30分鐘左右  
支持充電寶/手機充電器使用

Type-C charging socket  
After being fully charged, it can be used for about 30 minutes at a time  
Support the use of charging bank / mobile phone charger