


DIGITAL TIMER THERMO-HYGROMETER



OPERATION MANUAL



- Waterproof for water splashes, essential for your bathroom
- With large LCD display, easy to read, 12/24 hours selectable
- Indoor temperature and humidity display

DIGITAL TIMER

THERMO-HYGROMETER



SPECIFICATION

- Temperature Range: $-10^{\circ}\text{C} \sim +50^{\circ}\text{C}$ ($+14^{\circ}\text{F} \sim +122^{\circ}\text{F}$)
- Humidity Range: indoor 20%~90% RH
- Power-supply: 1.5V (AAA size) x 2

FUNCTIONS


- Temperature display, humidity display
- Temperature unit °C/°F changeable
- 2 modes of time display: 12h / 24h
- Count down/Count up
- Display timer range: 0~99 minutes
- Display of comfort degree
- ☺ appears @ Indoor Humidity 40%RH~70%RH and Temperature: 18°C~28°C (64°F ~82°F)
- ☹ appears @ Indoor Humidity lower than 40%RH or Higher than 70%RH,
- Comfort degree disappear when Indoor Humidity 40%RH~70%RH but the temperature is lower than 18°C(64°F) or higher than 28°C(82°F)

OPERATIONS

- Remove battery compartment cover. Remove tab under battery. Replace battery cover. The startup time defaults to AM 12:00

■ **BUTTON function:**

[SET] exchange display mode of TIME, 12h/24h display and Count down.

[-/ ] decrease the value of what is under setting or cancel the alarm sound.

[+ / °C/°F] change temperature unit between Celsius (°C) and Fahrenheit (°F) and increase the value of what is under setting.


[10] : in the countdown mode, press the [10] button to increase the countdown time by 10 minutes


[1] : in the countdown mode, press the [1] button to increase the countdown time by 1 minute

[CLEAR] : press [CLEAR] button to start or stop the countdown. Long press [CLEAR] button for 3 seconds to reset the countdown and return to the clock mode

■ **Clock setting:**

Under the clock state, long press the [set] button to set the time, at this time the hour flashes, press the [+] or [-] button to set the "hour" value, then press the "set" button to confirm, and then the "minutes" value flashes, press the [+] or [-] button to set the "minutes" value, then press the "set" button to confirm, after all the setting are finished, press the [set] button again to exchange the 12H/24H mode.

- Count-down settings, press the S/S button to enter the countdown settings, press the [10] button to increase 10 minutes and press the [1] button to increase 1 minute a time, press S/S button again after finish the settings to start the countdown, during counting down, press S/S button one time to pause, ,press S/S button one time again to restart the counting down from the pause point, under the status of pause for a long time or press CLEAR button for 3 seconds will come back to the time status. After the device counts down to zero, it gives off "beep" sound for about 3 minutes, Alarm will sound when countdown reaches 0. Press S/S to silence alarm. Alarm will continue sounding for three minutes if not cleared.
- Count-up setting, press the S/S button to enter the countdown settings and press the s/s button again to start the count-up.
- Press [+/^oC/^oF] button to change temperature unit:^oC/^oF
- Press [-/ ] button to cancel or activate the alarm sound. The screen appears ((•)) to indicate that the alarm sound is activated.
- Note: during setting, if without any operation in 15 seconds will return back to the original state.



ATTENTIONS

- In case any abnormal display occurs, please take out the power-supply battery and put back the battery after 2 seconds, then the meter returns to normal display.
- Please put away the replaced battery at the place appointed by Government.
- We will not inform separately in case of any changes made to this meter.