

Durchgangsmessung
Continuity check

Spannung / Voltage range:

AC 1000 V / DC 1000V

True RMS

Frequenz / Frequency

max. 60 MHz




Widerstand / Resistance

max 200 M Ω

CAT III 1000V / CAT IV 600V

inkl. Batterien / incl. batteries

inkl. / incl.



IS WIHA
GREEN?



WIHA.COM/
GREEN