



Power supply:  
110-240V~50/60Hz



2 hour fully charge  
60 minutes  
working time



High rotation silver pd.  
alloy motor

