


**BRAUCH  
SP130**

User manual of Hygrothermograph

◆ Product diagram



Note: it works directly when you open the package

◆ Product specifications

Temperature measurement range: -50 C ~ +70 C (-58 F ~ +158 F)  
Temperature measurement accuracy:  $\pm 1$  C (1.8 F)  
Temperature resolution: 0.1°C (0.2°F)  
Humidity measurement range: 10%RH-99%RH  
Humidity measurement accuracy:  $\pm 5\%$  RH  
Humidity resolution: 1%  
Power supply: CR2032\*1

◆ Basic functions

Temperature display  
Humidity display  
Comfort indicator


◆ Description of comfort level

Humidity display between 10%-39%, LCD display ☺.  
Humidity display between 40%-70%, LCD display ☺.  
Humidity display between 71%-99%, LCD display ☺.

**BRAUCH  
SP130**

Gebruikershandleiding van Hygrothermograph

◆ Product diagram



Let op: het werkt direct als je de verpakking opent

◆ product specificaties

Meetbereik temperatuur: -50 C ~ +70 C (-58 F ~ +158 F)  
Nauwkeurigheid temperatuur meting:  $\pm 1$  C (1.8 F)  
Temperatuur resolutie: 0.1°C (0.2°F)  
Meet bereik vochtigheid: 10%RH - 99%RH  
Nauwkeurigheid vochtigheids meting:  $\pm 5\%$  RH  
Vochtigheid resolutie: 1%  
Voeding: CR2032\*1

◆ Basis functies

Temperatuur weergave  
Vochtigheids weergave  
Comfort indicator

◆ Beschrijving van comfortniveau

Vochtigheidsweergave tussen 10% -39%, LCD-scherf ☺.  
Vochtigheidsweergave tussen 40% -70%, LCD-scherf ☺.  
Vochtigheidsweergave tussen 71% -99%, LCD-scherf ☺.