











PHILIPS


BT5211
BT5210
BT5207
BT5206
BT5205
BT5203
BT5201
BT5200
BT5190
























| BT5211, BT5210, BT5207, BT5206, BT5205 | | | | |
|--|-----|-----|-----|-----|
| mm | | | | |
| 0.4 | 0.6 | 0.8 | 1.0 | 1.2 |
| 1.4 | 1.6 | 1.8 | 2.0 | 2.5 |
| 3.0 | 3.5 | 4.0 | 4.5 | 5.0 |
| 6.0 | 7.0 | | | |



| BT5203, BT5201, BT5200, BT5190 | | | | |
|--------------------------------|------|-----|-----|-----|
| mm | | | | |
| 0.4 | 0.6 | 0.8 | 1.0 | 1.5 |
| 2.0 | 2.5 | 3.0 | 3.5 | 4.0 |
| 4.5 | 5.0 | 6.0 | 7.0 | 8.0 |
| 9.0 | 10.0 | | | |







www.philips.com

4222.002.8595.3