



Warning icons and assembly instructions:


- A warning icon consisting of a triangle with an exclamation mark, pointing to a crossed-out power drill icon.
- A warning icon consisting of a triangle with an exclamation mark, pointing to a clock icon.
- 30'**
- A warning icon consisting of a triangle with an exclamation mark, pointing to a crossed-out person icon.
- 1**




G x 3




E




F




C




D




B



A




H x 4



1

B





x 1

H




x 4





2

C




x 1



3

A




x 1


D




x 1



1a




1b




4

E




x 1


F




x 1



1a



1b



5

G



x 3

