




Diagram illustrating assembly instructions and warnings:

- Warning 1:** A warning triangle with an exclamation mark is shown next to a box containing an L-shaped metal bracket and a crossed-out power drill icon.
- Warning 2:** A warning triangle with an exclamation mark is shown next to a box containing a rectangular foam block on a mat and a crossed-out icon of a block being lifted.
- Time:** A clock icon is shown next to the text "40'".
- Person:** A stick figure icon is shown next to the number "1".




F




x 1

G




x 1

H




x 2

I




x 1

J




x 1

K




x 2

L



x 1


M



M4
x
20


x 16

N





x 16




!






1





2






3






4




5





6





7



8



9



!

