Follow all special requirements on packaging and labelling when transporting batteries by a third party. Ensure that no batteries can come in contact with other batteries or conductive materials while in transport by protecting exposed connectors with insulating, non-conductive caps or tape. Do not transport batteries that are cracked or leaking. Check with the forwarding company for further advice.

KNOW YOUR PRODUCT

See page 109.

- Battery port
- Lock-off button with unlock
- Handle, insulated gripping surface
- Spindle lock button
- 5. Lock-off button with lock
- On/off switch
- Side handle
- Guard lever lock
- Wrench
- Toolless grinding guard
- Locking flange
- 12. Toolless cutting guard attachment
- Grinding wheel
- Backing flange
- Spindle shaft
- 16. Operator's manual
- 17. Cutting Disc
- 18. Battery pack
- Charger

MAINTENANCE

- The product should never be connected to a power supply when assembling parts, making adjustments, cleaning, performing maintenance, or when the product is not in use. Disconnecting the product from the power supply will prevent accidental starting that could cause serious injury.
- When servicing, use only original manufacturer's replacement parts, accessories and attachments. Use of any other parts may create a hazard or cause product damage.
- Do not at any time let brake fluids, gasoline, petroleumbased products, penetrating oils, etc., come in contact with plastic parts. Chemicals can damage, weaken or destroy plastic which may result in serious personal injury.
- Avoid using solvents when cleaning plastic parts. Most plastics are susceptible to various types of commercial solvents and may be damaged by their use. Use clean cloths to remove dirt, carbon dust, etc.
- For greater safety and reliability, all repairs should be performed by an authorised service centre.

SYMBOLS ON THE PRODUCT



Safety alert

n

Rated speed

٧

Volts



Direct current

min⁴

Revolutions or reciprocations per minute



Please read the instructions carefully before starting the machine.



Wear ear protection.



0

Always wear eye protection.



Wear a dust mask.



Always operate the product with two hands.



Wear safety hand gloves.



Wear non-skid safety shoes.



Do not use a chipped, cracked or defective grinding wheel.



Do not use the product for cutting.



Do not use the guard for cut-off operations.



Use a guard.



Metal



Not for wet grinding. Using water or other liquid coolants may result in electrocution or shock.



Do not use for face grinding.



European Conformity Mark



British Conformity Mark



Ukraine Conformity Mark



EurAsian Conformity Mark



HU

RO

ET

SK

BG

UK

п

•

