


INSIDE YOUR COOLER.

THIS IS NORMAL AND NOT A DEFECT, WE SIMPLY ASK YOU TO WIPE THE CONDENSATION WITH A DRY CLOTH.

IF ANY FROST/ICE APPEARS INSIDE YOUR COOLER THIS WILL ALSO BE NORMAL, TURN COOLER OFF FOR A COUPLE OF HOURS, WIPE AWAY THE FROST/ICE AND COMMENCE NORMAL USE OF THE COOLER.

Please retain packaging for future reference.  
For technical support contact: [support@ukonic.com](mailto:support@ukonic.com)



**UK  
CA**

**CE**



Veuillez conse  
Pour le support

AUTOUR DE  
PROBABLE QU  
À L'INTÉRI  
C'EST NORMA  
DEMANDO  
CONDENS  
SI DU GIVRE  
L'INTÉRIEUR  
AUSSI NOR  
PENDANT  
GIVRE/LA GL