


ASSEMBLY INSTRUCTIONS

MATERIALS CAREFULLY.FOR SMALL PARTS.WHICH MAY HAVE COME LOOSE INSIDE THE CARTON.
DURING SHIPMENT.IDENTIFY AND COUNT ALL PARTSAND COMPARE WITH THE HARDWARE
LIST AND PARTSLIST.



A		M8*20MM	16
B		M8*65MM	6
C		M6*55MM	3
D		M8	6
E		M5	1
F		14#	1
G			24
H			24
I			12
J			3

1.

2.

3.

4.

5.

6.