

Product Analysis



1 / 4 screw

Cold Shoe Mount

Display



Power on / off
Adjustment driving plate 1

1 / 4 screw

Adjustment driving plate 2

Type-c charging port

Power on / off :

- ① long press : power on / off
- ② Short press : mode switch

Adjustment driving plate 1:

- ① In CCT mode : Turn the wheel to adjust the color temperature
- ② When in RGB mode : turn the wheel to adjust the color tone
- ③ In HSI mode : turn the wheel to adjust the saturation tone
- ④ In SCENE mode : turn the wheel to switch the special effect scene

Adjustment driving plate 2:

Rotate the wheel in any mode to adjust the brightness



1.6cm

11.5cm

7cm