



Functions	Range	Resolution	Accuracy
Noise (A Weighting)	30~130dB	0.1dB	±1.5dB
Sampling Rate	FASH		125ms
	SLOW		1000ms
Overload Indication			OL
MAX/MIN			MAX/MIN
Data Hold			HOLD
LCD Backlight			Yes
Auto Power Off			5min
Low Battery Indication			3.0~3.5V
Battery			4.5V
Current Consumption	Working	mA	≤40mA
	Power off	uA	≤10uA
Working Environment	Temperature		0~40℃
	Humidity		≤80%RH
Storage Environment	Temperature		-20~60℃
	Humidity		≤75%RH
<b>Key Functions</b>			
ON/OFF	Short press to turn on/off the meter		
MAX/MIN	Short press to switch between MAX/MIN/normal measurement state		
FAST/SLOW	Short press to select fast sampling (125ms) or slow sampling (1s)		
HOLD/BL	Short press to enter data hold mode, long press to turn on/off backlight		