










An icon showing an L-shaped metal bracket inside a circle, and a power drill with a diagonal line through it, indicating that a drill should not be used.	A warning triangle with an exclamation mark inside.	A clock face icon.
<p>30'</p>		
An icon showing a rectangular block on a textured base inside a circle, and a similar block with a screw being inserted into it, with a diagonal line through it, indicating that screws should not be used.	A warning triangle with an exclamation mark inside.	A simple icon of a person.
<p>2</p>		

A	B	C	D	E
		 M6 x 15		
x 1	x 4	x 12	x 12	x 1






A



B x 4



1

<p>A</p>  <p>x 1</p>	<p>B</p>  <p>x 4</p>	<p>C</p>  <p>M6 x 15</p> <p>x 12</p>	<p>D</p>  <p>x 12</p>	<p>E</p>  <p>x 1</p>
---	---	---	--	---

