


























60'






2







<p>5</p>  <p>x 1</p>	<p>6</p>  <p>x 1</p>	<p>7</p>  <p>x 2</p>	<p>8</p>  <p>x 2</p>		
<p>9</p>  <p>x 4</p>	<p>10</p>  <p>x 2</p>	<p>11</p>  <p>x 1</p>	<p>12</p>  <p>x 1</p>		
<p>A1</p>  <p>x 10</p>	<p>A2</p>  <p>x 10</p>	<p>A3</p>  <p>x 10</p>	<p>B</p>  <p>Ø8 x 30</p> <p>x 16</p>	<p>C</p>  <p>M6 x 50</p> <p>x 6</p>	
<p>D</p>  <p>x 1</p>	<p>E</p>  <p>M3.5 x 16</p> <p>x 24</p>	<p>F</p>  <p>M4 x 25</p> <p>x 2</p>	<p>G</p>  <p>M4 x 38</p> <p>x 16</p>	<p>H</p>  <p>x 12</p>	
<p>I</p>  <p>M6 x 35</p> <p>x 4</p>	<p>J</p>  <p>M6 x 70</p> <p>x 4</p>	<p>K</p>  <p>x 4</p>	<p>L</p>  <p>x 2</p>	<p>M1</p>  <p>x 4</p>	<p>M2</p>  <p>x 4</p>






1








2





3





4



5



6






7

A3




x 10



8

2




x 1

C





x 6



D





x 1






9





10








11 x 2







12 x 2



13 x 2



14 x 2



15

