


Diagram illustrating assembly instructions and safety warnings:


- Warning 1:** A warning triangle with an exclamation mark is positioned above a box containing:
 - A circular icon showing a corner bracket.
 - A crossed-out power drill.
- Warning 2:** A warning triangle with an exclamation mark is positioned above a box containing:
 - A circular icon showing a rectangular block on a textured surface.
 - A crossed-out rectangular block with a screw being inserted into its bottom.
- Time:** A clock icon is shown next to the text "15'".
- Person:** A stick figure icon is shown next to the number "1".

A




x 1

B



x 4

A



B x 4

