


## Operation

1. To turn on the thermometer, pull the probe away from the thermometer body. The LCD screen will turn on, display all options, then display the current probe temperature. To turn off, Press and Hold the "ON/OFF" button.
2. The thermometer is set to display temperatures in degrees Fahrenheit ( Celsius ). To switch to Celsius ( Fahrenheit ), Press the "C/F" button.
3. To check the temperature insert the probe into the thickest part of the food.
4. Data-Hold. Before withdrawing the probe from the food, press and hold "HOLD" button. It will display the temperature reading until pressed again.
5. The temperature will be displayed on the LCD screen.
6. The thermometer will turn off automatically after 10 minutes if no other buttons are pressed.
7. To change the battery, open the case on the reverse side of the thermometer. Replace with an CR2032 battery.
8. To illumine the screen , Press the  button .