## • FAQ and Treatment

No.	Problem	Possible Cause	Trouble-shooting
1	Sneezing or clicking noise heard during the action	The noise of normal operation or the abrasion of massage bal and cloth cover	No need to process
	Fails to boot	Overheat protection	Close for 30m and reboot
2		Power plug or cigar lighter socket is not well inserted	Insert it again
4:		Reversing switch is on its middle position	Switch to left or right

If there is still any unusual problems, please contact local dealer for maintenance or repair.

## **Warranty Card**

Dear Users:

Thank for your choice on products, we will be dedicated to serve you. The products are provided one-year-free repair for no man-made damages since the date of purchase.

Name of user	Contact phone	P.C.	
Specific address			
Date of purchase	Shop purc	Shop purchased	
Model NO.	Service T	el.	







## CAR&HOME MASSAGE PILLOW

1 Strong air permeability 2 One button smart start
3 Far-infrared heating 4 Ultra-thin fashionable shape

Please read carefully operation instructions before using