


Product specification:



Scale

Capacity	3000g
Min. weight	0.3g
Division	0.1g (0.3- 500g) 0.5g (501-1000g) 1g (1001-3000g)
Units	g/oz/ml
Timer	
Display	4-Digital LED
Maximum count up time	99 minutes 59 seconds
Power source	DC4.5V 3XAAA batteries
Automatic power off	3 minutes

Operating:

- ① Press "ON/OFF" to display "HELLO".
After stable, display shows "0'00" 0.0g.
- ② Put the items on the weighing pan to weigh.
- ③ If the display unit is not right, you can press the "UNIT" key to achieve unit conversion, select the unit you want to use.

Tare Function:

- ① Put a tray or container to the pan.
- ② Press "TARE" key, the display will show "0.0"g.
- ③ Then you can add items to the container or weighing plate weighing.
- ④ When the container and contents are removed "-" will be displayed.

Timer Function:

- ① Press "START/STOP" key to start the timer.
- ② Press "START/STOP" key once to pause the timer.
Press "START/STOP" key again to resume timer.
- ③ Press and hold "START/STOP" key will timer to zero.