

with an output voltage of DC 5V and an output current of less than 0.5A - anything above that may cause the device to overheat or even explode. Do not light the arc for more than 10 seconds at a time. Do not expose the device to temperatures above 50°C, and keep it out of direct sunlight. Do not place the unit near flames or sparks. Never leave the device unattended while charging and always disconnect the device from the power source once it is fully charged.



www.perow.nl
Postbus: 145737 ZG Lieshout



MADE IN CHINA

MODEL: HY-XL1001