


Assembly instruction | Slim metal cross base



Seat options



Included parts

A x1	B x1
Seat	
* C x4 (M6*16)	D x4 (M6*16)
E x4 (M6)	

*** ATTENTION!**

For upholstered shell use different parts

[C] -> M6*18 screws

