

long press for 2 seconds to turn on/off.
short press to switch to cold/natural/warm
color light mode

Brightness switch button

after boot, short press it to switch to
medium/high/low light

Use with other tripods

the product is built standard 1/4" screw
mount, compatible for tripods with
corresponding interface

Charge

the product has a usb charging port,
please use usb cable to charge it when
the battery is used up.

red indicator light will go on during
charging and go out after fully charged



input voltage:5V input current :1A

MADE IN CHINA

CE RoHS