C The CE mark indicates that the product was assessed by the manufacturer or Notified Body and is safe according to EU requirements. Personal protective equipment (PPE) conformity with the essential health and safety requirements is set out in Regulation (EU) 2016/425 of 9 March 2016 repealing Council Directive 89/686/EEC. It defines legal obligations by different economic operators to ensure that PPE provides the required level of protection against risks at the workplace. The Regulation also lays down requirements for the design and manufacturing of the PPE.

HELLY HANSEN Workwear PPE products are manufactured, tested, and certified according to the harmonised standards under PPE Regulation. The products provide protection and prevention against possible accidents or injuries when working under conditions involving cold, heat, flame, rain, reduced visibility, etc.

The PPE is classified according to three risk categories based on risks for user health and safety:

Category 1 includes exclusively minimal risks such as rain, cool environments, or electrostatic charge.

Category 2 includes risks that are not covered by Category I or Category III. That may cover dangers in reduced visibility or cold environments.

Category 3 includes risks that may cause irreversible damage to health or place the user to mortal danger, such as electric arc.

The CE mark provides documentation that the product complies with performance standards set for a product of such nature. It is not an assurance that the product will prevent risk of accidents or severe injuries when the user is exposed to such risks in a working environment. Below is a condensed presentation of the harmonized European (EN) standards used in the HH Workwear collection.

For complete information about the CE marking system, please contact our representative or the local authorities.

* The test data is given as an integral part of the symbol as measured to prescribe methods on a scale from 1 to 3, whereby 3 is the highest level.

* The actual data for a HH product is given on the inseam label and on the booklet attached to the garment as well as in the product section of this brochure and at <u>https://www.hellyhansen.com/</u>