





Assembly step 1: A box containing icons for an L-shaped bracket, a wrench, and a power drill with a slash through it, indicating that a power drill is not required. To the right of the box is a warning triangle with an exclamation mark. Further right is a clock icon showing approximately 30 minutes, with the text "30'" below it.

Assembly step 2: A box containing icons for a mattress and a diagram showing a mattress being placed on the slatted base with a slash through it, indicating that the mattress should not be placed on the slats. To the right of the box is a warning triangle with an exclamation mark. Further right is a person icon with the number "2" below it, indicating that two people are required for this step.




A




x 28

B




x 8

C




x 8

D




x 8

E




x 16

F






x 1

G






x 1





1







2






3






4






5






6



7 x2





8




9

F
x1




10 x13

7




x2

8




x2


9



x3



1a



1b

