










An L-shaped metal bracket is shown inside a circle. To its right is a power drill with a diagonal line through it, indicating it should not be used.	A warning triangle containing an exclamation mark.	A clock face showing approximately 12:30.
A rectangular block is shown on a surface with a diagonal line through it. To its right is a similar block with a screw being inserted into it, also with a diagonal line through it, indicating it should not be done.	A warning triangle containing an exclamation mark.	A simple icon of a person.
<b>30'</b>		<b>1</b>




1



2





3






A


C



4



5



!

